DEPARTMENT OF TRANSPORTATION


REPORT OF BRIDGE SURVEY


U.S. COAST GUARD CG-2541-D11 (Rev2/99)

INSTRUCTIONS: 1. Submit this report to the Auxiliary Coordinator as soon as possible after conducting the survey.

- 2. The best time to survey bridges is shortly betore sunset so you can observe any hazards or discrepancies before dark, then observe the lights after dark.
- 3. If conducting the survey by land, respect all property rights. DO NOT TRESPASS.
- 4. Auxiliarists do not have law enforcement authority. Take care that your survey is not interpreted as a law enforcement action.
- 5. Minor discrepancies (e.g. one light out, clearance gauges hard to read) should be reported by mail. More serious problems (e.g. most or all lights out, hazards to navigation, bridge malfunction) should be reported to the nearest Coast Guard Group Office by telephone or radiotelephone. If in doubt, report it.

reported to the nearest Coast Guard Group Office by telephone or radiotelephone. If in doubt, report it.							
NAME OF BRIDGE					ATITUDE		LONGITUDE
BAY FARM ISLAND	AND BIKE BRIDGE				37 44.9' N		122 14.2' W
NAME OF WATERWAY					MILES ABOVE MO	UTH	TYPE OF BRIDGE
SAN LEANDRO BAY					0.1		В
NAME/ADRESS OF BRIDGE OWNER				NAME/ADDRESS OF BRIDGE OPERATOR (if different)			
City of Alameda				County of Alameda DPW			
City Hall				399 Elmhurst Street			
Alameda	CA 94501			Alameda			<u>CA</u> 94544
Fill out the section below and annotate the diagram on the reverse. Show north arrow or direction of current.							
TYPE OF LIGHTS	Number of Lights	Are Lights Correctly Placed?	of F	Lights Proper or/Arc?	Visible for		State Condition of Lights
Channel Center Lights	0						
Margin of Channel Lights	0						
Pier Lights	2						
Pier Axis Lights	0						
Movable Span Lights	2						
Preferred Channel Lights	0						
OTHER FEATURES	How Many?	LLNR	Chara	acteris	tic Range		Working Properly?
Fog Signals	0	0		N/A	N/A		
Raco ns	0	0	١	N/A	N/A		
Condition of fenders:	Condition of vertical clearance gauges:						
Is the bridge name shown? What name is shown?							Is sign visible to mariners?
Are navigational clearances impaired by disrepair, cables, etc? Are nav. clearances impaired by accumulation of debris?							
Is there any equipment (e.g. barges, scaffolds) in the navigation spans that is not listed in the LNM/BNM?							
If a drawbridge, is it capable of operating? Are the operating regulations posted?							Discrepant
Is there evidence of bridge or fender damage that might be from vessels?							Watching properly
Date and Time of Survey	Name and Member Number						Home Telephone Number
	Signature of Surveyor						Aux. File Number 41





San Leandro Bay

Single-leaf Bascule

Bay Farm Island Bike Bridge (Otis Street) pier lights are only on one side due to the proximity of the highway bridge